



INFRARED SCANNING

Trumbo Electric is pleased to offer a full line of diagnostic and preventative maintenance services to our customers. One of the primary diagnostic methods is the technology of Infrared Scanning. Infrared Scanning (Thermal Imaging) is unsurpassed in its ability to identify potential problems in your electrical distribution system. One of the greatest benefits of thermal imaging is the ability to perform a complete system scan without interruption to your day-to-day operations. Because all scanning is performed while the electrical system is energized, we are able to identify potential problems that would not be evident if the equipment was in a de-energized state. Our thermal imaging technicians along with our highly qualified engineering staff can provide you with the options to customize a scan to suit your facilities' needs.

THERMAL IMAGING OVERVIEW

What is a Thermal Image?

A Thermal Image is a measure of the heat given off by an object; recorded as a digital image.

How does a Thermal Image help predict electrical problems?

The equipment in a Thermal Image is compared to its suggested temperature ratings as well as the objects around it to determine if any significant temperature rises exist.

Do all temperature rises indicate a potential failure?

No, our engineering staff will review each image to determine if any problems exist. Any problems will be identified and prioritized accordingly.

How are problems identified?

Severe problems will be brought to your attention by our technician during the scan, while all other problems are identified in reports generated after the scan has been completed and reviewed. The report will include both digital and infrared images to document all problems identified.

How are problems repaired?

Repairs are not included as part of the scan; however, small repairs such as a loose screw will be repaired during the scan. While additional repairs are at your discretion, we will gladly assist you in planning and performance of the repairs.

TRUMBO ELECTRIC, INC. THERMOGRAPHIC REPORT			
COMPANY NAME:	YOUR FACILITY		
ADDRESS:	YOUR ADDRESS		
INSPECTOR:	OUR TECHNICIAN		
TRUMBO ELECTRIC, INC. BROADWAY, VIRGINIA 22815			
EQUIPMENT IDENTIFICATION:	PANEL ABC		
EQUIPMENT TYPE:	225 A PANELBOARD		
EQUIPMENT LABEL NUMBER:	00472		
PROBLEM DESCRIPTION: SOME SEVERE TEMPERATURE RISE ON CIRCUIT BREAKER			
RECOMMENDED ACTION: CHECK FOR OVERLOADING AND POSSIBLE LOOSE CONNECTIONS AT BREAKER AND PANEL			
REPAIR PRIORITY: (LOW, MEDIUM, HIGH):			
INSTR:			
THERMOGRAM REFERENCE IMAGES AND INFORMATION			
IMAGE DATE:	5/2/2000	DIGITAL PHOTO #:	00013
EMISSIVITY:	0.95	THERMAL IMAGE #:	00100
			

Trumbo Electric, Inc.
258 North Timber Way, Post Office Box 38, Broadway, Virginia 22815 (540) 896-7095